

SOIL/SITE EVALUATION for ON-SITE WASTEWATER SYSTEM

OWNER: CRI APPLICANT: _____
ADDRESS: _____ APPLICATION DATE: _____ DATE EVALUATED: 3-12-99
PROPOSED FACILITY: _____ PROPOSED DESIGN FLOW (.1949): _____ PROPERTY SIZE: _____
LOCATION OF SITE: Lot 288 phase 3 Theft PROPERTY RECORDED: _____
WATER SUPPLY: ☐ Private ☐ Public ☐ Well ☐ Spring ☐ Other _____
EVALUATION METHOD: ☐ Auger Boring ☐ Pit ☐ Cut _____
TYPE OF WASTEWATER: ☐ Sewage ☐ Industrial Process ☐ Mixed _____

PROFILE #	1940 LAND-SCAPE POSITION/SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941)		OTHER PROFILE FACTORS				PROFILE CLASS & LTAR
			.1941 STRUCTURE/TEXTURE	.1941 CONSISTENCE/MINERALOGY	.1942 SOIL WETNESS/COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	
1	#116 TOS	0-4	brn sl						P5 13
		4-32	wh br AC	fr ssd					
		32-49	stn yrd	fr ssd					
2		0-5	sl						P5 13
		5-48	R/c						
		48-65	hard silt/cl						

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM	OTHER FACTORS (.1946):
Available Space (.1945)			SITE CLASSIFICATION (.1948):
System Type(s)			EVALUATED BY:
LTAR			OTHER(S) PRESENT: