

SOIL/SITE EVALUATION FOR

ON-SITE WASTEWATER SYSTEM

APPLICANT: Paul Blythe OWNER: _____ AGENT: _____ PHONE: 892-0286
ADDRESS: _____ APPLICATION DATE: 3/21/97 DATE EVALUATED: 4/15/97
PROPOSED FACILITY: _____ PROPERTY SIZE: _____

LOCATION OF SITE: Lot 31 Spring Acres
WATER SUPPLY: On-Site Well ☒ Comm. Well _____ Public _____ Other _____ EVAL. METHOD: Auger Boring ☒ Pit _____ Cut _____

PROFILE #	.1940 LANDSCP POS. (%)	HORIZON DEPTH (IN.)	.1941 STRUCTURE/TEXTURE	.1941 MINERALOGY/ CONSISTENCE	.1942 WETNESS COND.	.1944 RESTRICT HORIZONS	.1948 CLASS OF HORIZ	1943/ 1956 SAPRLT CLASS.	HORIZON LTAR
1	CL L 90%	0-5	SBK / l	1:1 S NP					
		6-17	SBK / cl	SBK 1:1 S SP					
		18-33	wk SBK / cl	1:1 S P					.25
		34-39	wk SBK / l	1:1 SS SP					.35
		40-48	wk SBK / l	1:1 SS SP					
2	w	0-10	wk / cl	1:1 SS SP					
		11-19	wk GR / sel	1:1 SS SP					.25
		20-47	GR / cl SAP	1:1 SS SP					.3
3									
4									
5									

AVAILABLE SPACE (.1945) _____ SITE CLASSIFICATION (.1948): _____ SITE LONG-TERM ACCEPTANCE RATE: _____

EVALUATED BY: _____ OTHER(S) PRESENT: _____

COMMENTS: 4 - ch - Plastic Chamber