

SOIL/SITE EVALUATION for ON-SITE WASTEWATER SYSTEM

OWNER: Chris Tucker Traditional Southern Homes APPLICATION DATE
ADDRESS: DATE EVALUATED: 11-29-05
PROPOSED FACILITY: Residential PROPOSED DESIGN FLOW (.1949): PROPERTY SIZE:
LOCATION OF SITE: Spring Acres Lot 22 PROPERTY RECORDED:
WATER SUPPLY: ☒ Private ☐ Public ☐ Well ☐ Spring ☐ Other
EVALUATION METHOD: ☒ Auger Boring ☐ Pit ☐ Cut TYPE OF WASTEWATER: ☒ Sewage ☐ Industrial Process ☐ Mixed

P R O F I L E #	.1940 LANDSCAPE POSITION/ SLOPE %	HORIZON DEPTH (IN.)	SOIL MORPHOLOGY (.1941)		OTHER PROFILE FACTORS				PROFILE CLASS & LTAR
			.1941 STRUCTURE/ TEXTURE	.1941 CONSISTENCE/ MINERALOGY	.1942 SOIL WETNESS/ COLOR	.1943 SOIL DEPTH	.1956 SAPRO CLASS	.1944 RESTR HORIZ	
1	slight head - linear	0-10	1sbk1						.3
		10-20	1sbkSI						
		20-36	1sbksc1			48			
		36-48	1sbkC						
2	Initial 2390	0-15	1sbkC1						.25
		15-48	1sbk/abkC	fr ss/spSE		48			
3	Repair	0-10	1sbkSI						.25
		10-22	1sbksc1						
		22-36	1sbkC	fr ss/spSE		48			
		36-48	1sbk/abkC	fi ss					
4	27% Repair area	0-20	1sbksc1						.3
		20-48	1sbkC1			48			

DESCRIPTION	INITIAL SYSTEM	REPAIR SYSTEM	OTHER FACTORS (.1946):
Available Space (.1945)	yes	yes	SITE CLASSIFICATION (.1948): <u>ps</u>
System Type(s) <u>gravity</u>	<u>25% fed.</u>	<u>Panel</u>	EVALUATED BY: <u>Judy Melville</u>
Site LTAR	<u>.25</u>	<u>.25</u>	OTHER(S) PRESENT: <u>Chris Tucker</u>

COMMENTS: 4 @ 120'